

**Search Notes****Application/Control No.**

10/771,083

**Examiner**

Toan M. Le

**Applicant(s)/Patent under Reexamination**

HOFMEISTER ET AL.

**Art Unit**

2863

**SEARCHED**

Class	Subclass	Date	Examiner
702	120	5/24/2005	TL
372	38.1	5/12/2005	TL
372	50	5/12/2005	TL
257	688	5/20/2005	TL
385	92	5/20/2005	TL
385	93	5/20/2005	TL
372	38.02	5/23/2005	TL
Above	Updated	12/22/2005	TL

**INTERFERENCE SEARCHED**

Class	Subclass	Date	Examiner

**SEARCH NOTES  
(INCLUDING SEARCH STRATEGY)**

	DATE	EXMR
Electrostatic Discharge Damage, Photodiode, Laser	5/12/2005	TL
Laser Diode, Switch, Transceiver, Pins	5/12/2005	TL
Transceiver Module, Laser Diode	5/12/2005	TL
VCSEL, Laser Drive, Laser Diode, Transceiver	5/23/2005	TL
702/120; 372/38.1,50,31; 257/688; 385/92,93; 398/135 (Laser Diode)	12/22/2005	TL
East-See Search History Printout	12/22/2005	TL
IEEE Xplore, Web	12/22/2005	TL